Resistance of mounted assemblies to temperature cycling



Kiwa Nederland B.V.

. . .

Kiwa report number	LC 17207					Lab C Wilmersdorf 50 NL 7327 AC Apeldoorn Netherlands			
Date of report	25-9-2019					Telephone Internet	+31 (0) 088 998 3393 www.1kiwa.com		
Total number of pages	6								
Performed request	Determination of the resistance of mounted assemblies to temperature cycling								
Requested by	Kiwa Nederland B.V. Sir Winston Churchilllaan 273 NL-2280 AB Rijswijk								
Client	Wavin TR Adana (TR)								
Tested products	Pipes	1) 2)	Wavin Wavin	TR, PE-Xa-barrier TR, PE-RT type II	⁻ pipes barrier- p	ipes			
	Fittings	Wav	vin Sma	artFix push fit fitting	gs				
Test method	EN 12293 :19	999		Plastics piping sys fittings for hot and resistance of mou	stems - Th I cold wate inted asse	nermoplastic er - Test me emblies to te	cs pipes and thod for the emperature cycling		
Referring documents	ISO 15875-5 / ISO 22391-5								
Reference number	190600091								
Requirements	No leakage during testing of the assembly and no delamination of the multilayer pipes								
Conclusions*	nclusions*The assembly (pipe-fitting combination) did meet the requirements for no leakage of the assembly during testing* This conclusion is not part of the scope of the RvA accreditation L015.						ts for no leakage		
							n L015.		
Authorised by									

Mr. Henk Pauw, Coordinator Lab C

- The test results in this report are exclusively related to the samples offered and tested.
- With regard to measurement uncertainty information please check our website.

⁻ This report may only be duplicated as a complete set. without any modifications and with permission of the legitimate owner.

⁻ In case of dispute regarding this test report please contact Kiwa Nederland B.V.



Determination of the resistance of mounted assemblies to temperature cycling

1 Sample definition

Piping system : Commercial name Temperature profile ISO 10508 Design pressure Rigid/Flexible		Not specified Class 5 6 bar Flexible (C1 in figure 1)
Pipes, type 1:		
Manufacturer	:	Wavin TR
Production location	:	Adana (TR)
Commercial name	:	Not specified
I ype of material/construction	:	PE-Xa pipes
Dimension	÷	16 mm
Colour Inside/outside	÷	Natural / Natural 20 MTS VASCO DE Vo 16 V 2 5 Lovor SKZ A 727
Marking	•	CLASS 4 SURFACE HEATING-COOLING 8 bar EN ISO
		15875-2 OXYGEN BARRIER EN ISO 21003-2 11/02/19
		14:45 L-4
Date of production	:	Not specified
Pipes, type 2:		
Manufacturer		Wavin TR
Production location	÷	Adana (TR)
Commercial name	:	Not specified
Type of material/construction	:	PE-RT Type II pipes
Dimension	:	16 mm
Colour inside/outside	:	Natural / red
Marking	:	Wavin Pilsa ISO 22391-2 OKSIJEN BARIYERLI PE-RT Tip2
		Ø16"2.0 mm Boyut Sinifi : C 53,5 Uygulama SINIFI :1/10- 2/8-4/8-5/8 Makina No:16 20/02/2019 17:32 119MI >< Wavin
		Pilsa
Date of production	:	Not specified



Determination of the resistance of mounted assemblies to temperature cycling

Fittings : Manufacturer Type of material/construction	:	Wavin Brass push fit fitting (transition couplers) PPSU push fit fitting (Elbow/Straight-couplers)
Type of fittings transition couplers		
- number	:	2
- dimensions	:	16 mm $\times \frac{1}{2}$ " male thread
- marking	:	wavin 16 mm
straight couplers		
- number	:	4
- dimensions	:	16 mm
- marking	:	wavin 16 mm
elbows		
- number	:	4
- dimensions	:	16 mm
- marking	:	wavin 16 mm

2



Determination of the resistance of mounted assemblies to temperature cycling



Figure 1, schematic representation of the typical assembly for two types of pipes and one type of fitting

3 Apparatus

The equipment is in accordance with EN 12293:1999. The equipment is a thermal cycling testing apparatus manufactured by IPT Germany.

4 Test method

The test method used is in accordance with EN 12293:1999.



Determination of the resistance of mounted assemblies to temperature cycling

5 Test parameters

Test pressure	:	(6±0,2) bar
Test temperature cold	:	(20±2) °C
Test temperature hot	:	(93±2) °C
Temperature difference in/out	:	< 5°C
cycle time cold	:	(15 ⁺¹ / ₋₀)min
cycle time hot	:	(15 ⁺¹ / ₋₀)min
total cycle time	:	(30+2/-0)min
alteration time cold \rightarrow hot	:	≤ 60 sec
alteration time hot \rightarrow cold	:	≤ 60 sec
Water velocity	:	>0,5 m/s
Number of cycles	:	> 5000 (see test results)
Environment	:	water in air
Environmental temperature	:	(23±5)°C
Applied pre tensile stress	:	(229±1)N
Bending radius branch C1	:	0,96m
Conditioning period	:	1 h
Accuracy pressure equipment	:	+2%/-1%
Number of tested assemblies	:	1
Number of joints tested	:	18
Construction assembled by	:	Kiwa
Date received at Kiwa Lab C	:	05-06-2019
Test started at	:	05-06-2019
Test performed by	:	Mr B. Bonekamp

6 Test results

Number of cycles executed	:	> 5000
Signs of leakage		
- pipe	:	No
- fitting	:	No
- jointing	:	No
Observation of delamination	:	No
remarks	:	None

7 Remarks

None

8 Conclusions*

The tested joints as described above did not show any failure and no leakage was observed during testing time.

* This conclusion is not part of the scope of the RvA accreditation L015.

9



Determination of the resistance of mounted assemblies to temperature cycling

<text>

Photo 2: Straight coupler



Photo 3: Elbow, connecting type and type 2 pipes

